CORRESPONDEN		
INCOMING LETTER		
	_	
1665200E	2	سار
المنظمة المسترك نبذا		$\leq$
ACTION:		
1 ten Der	74	Ϋ́
OF CANA	, _,	1
2000		
		-
DUE DATE / () - 15	- =	<u>.</u>
		4
DISTRIBUTION		Ħ
	1-1	프
7 CON DIA		
NELSON, RM	1 1	_
SIMONSON, DP	M	
PAUOLE, AH	1	
		_
7151107 141		
BISHOP, ML		
BRAINARD, B	1 1	
FESS. G	1	
KAROL, MS	<del>;                                    </del>	
	•	_
LOCKHART, F		-
SARGENT, D	1 1	ļ
	Ti	_
WONG, D		
	1 1	]
ANDERSON, TW	1 1	1
LUKOW, TE	Ι¥	-
		ᅴ
OLINGER, S		
OUINN, D RASK, WC	1 1	
RASK, WC		
RAU. E		
	-	
RILEY, DR	1 1	_
RUSCITTO, DG	1 1	- 1
	3 1	
CC11/100 D C ROLL		
<u> </u>	<u> </u>	-
COE DG		_[
DUFFY, GG	1 1	- 1
GRETHEL T	i	-1
HUFFMAN ON		-
	•	_
MTLLER, HG		
OSTMEYER, RM		
DEECE D	1	
I PETT CH	1	
	!!	—l
CLEMITSU ID	1 1	]
VANDERPUY, M	X	
		ᅥ
	<del>! !</del>	-1
		- 1
	1 1	,
	+	_
W/P		$\exists$
W/P	l XI	
W/P RECORDS		X
RECORDS	l XI	X
RECORDS	l XI	X
	l XI	X
RECORDS	l XI	X
NOTE:	l XI	
RECORDS	l XI	X
NOTE:	l XI	
NOTE:	l XI	
NOTE:  NOTE:  Particular description of the second of the	l XI	
NOTE:	l XI	
NOTE:  NOTE:  Particular description of the second of the	l XI	
NOTE:  NOTE:  Particular description of the second of the	l XI	

DOERFO

EGÉG ROCKY FLATS

RECEIVED

U.S.D.O.E.

BOOKY FLATS, INC.

ROCKY FLATS PLANT, P.O. BOX 464, GOLDEN, COLORRODO 80402-0464 - (303) 966-7000 EG&G ROCKY FLATS, INC.

1990 DCT -2 P 3 02

Robert M. Neison, Jr. Manager DOE RFO

POND B-1 AND POND B-2 TRANSFER TO POND A-2

The first two ponds in the South Walnut Creek Drainage (Pond B-1 and Pond B-2) are non-discharge ponds and are used for diversion of effluent from the Sewage Treatment Plant (STP) when a suspected upset is being investigated, and for diversion of plant runoff for spill containment purposes. Pond B-1 is currently near 100% capacity, and Pond B-2 is at greater than 50% capacity.

We propose that approximately 500,000 gallons of water be pumped from Pond B-1 to Pond A-2, and that approximately 700,000 gallons of water be pumped from Pond B-2 to Pond A-2. Pond A-2 is a non-discharge pond with a water storage capacity greater than 6,000,000 gallons, and is currently near 10% of this capacity. The addition of 1,200,000 gallons of water to Pond A-2 would not jeopardize spill control capabilities. This transfer of water will provide needed storage capabilities for Pond B-1 and Pond B-2, and will also support B-1 dam improvements which are in the planning stage.

We have sampled and analyzed the water in Pond B-1 and Pond B-2. Results for Pond B-1 show no organic or metallic constituents of concern, and values for gross alpha/beta are within acceptable ranges. Results for Pond B-2 showed values of 4 and 7 ppb Trichloroethene. No other organic or metallic constituents of concern were found, and values for gross alpha/beta were within acceptable ranges.

Detailed results for parameters sampled can be obtained by contacting L A. Dunstan, Clean Water Act Division, Ext. 5743.

Kersh, Associate General Manager

Environmental Restoration and Waste Management

DY:fm

Orig. and 1 co - R. M. Nelson, Jr.

90-RF-6018